



# EUROPEAN SOUTHERN OBSERVATORY

Organisation Européenne pour des Recherches Astronomiques dans l'Hémisphère Austral  
Europäische Organisation für astronomische Forschung in der südlichen Hemisphäre

ESO - European Southern Observatory  
Karl-Schwarzschild Str. 2, D-85748 Garching bei München

---

## Very Large Telescope Paranal Science Operations FLAMES Calibration Plan

Doc. No. VLT-PLA-ESO-13700-3248

Issue 90, Date 24/02/2012

Prepared ..... J. Smoker  
Date Signature

Approved ..... A. Kaufer  
Date Signature

Released ..... C. Dumas  
Date Signature

This page was intentionally left blank

### Change Record

Issue/Rev.	Date	Section/Parag. affected	Reason/Initiation/Documents/Remarks
0.1	22-12-02	All	Created from UVES Cal.Plan [3]
	11-01-03	All	1st Draft
0.2	26-01-03	All	IOT comments included
	01-02-03		QC aspects included together with R.Hanuschik
0.3	21-07-03		more comments added (L.Pasquini, R.Hanuschik)
0.4	26-07-03		ARGUS added
			ARGUS specphot
			GIRAFFE Maintenance
1.0	01-02-04		No changes apart from document number added
1.1	06-06-04	Appendix 1	Calibration time added
2	25-11-04		Minor changes
79	06-12-06		Changing the format to comply with ESO rules
81	26-08-07		Version updated
82	08-03-08		Version updated
83	23-11-08		Version updated
84	25-02-09		Version updated and comment added about very long times for blue attached flats
85.0	28-08-09	3.2, 4.1.3, 4.5.2, 4.9, 5.2.4 4.6.2	Validity interval, attached flatfield, standard star sections altered. Layout improved.
			Comment about ThAr SimCal contamination added.
87	25-08-10		Version updated
88	01/03/2011	none	Version for Period 88 Phase I and II
89	30/08/2011	none	Version for Period 89 Phase I and II
90	24/02/2012	none	Version for Period 90 Phase I and II

This page was intentionally left blank

# Contents

<b>1</b>	<b>Glossary</b>	<b>1</b>
<b>2</b>	<b>List of acronyms and abbreviations</b>	<b>2</b>
<b>3</b>	<b>Introduction</b>	<b>3</b>
3.1	Overall description of the document . . . . .	3
3.2	Note on frequency of calibrations / validity times . . . . .	4
<b>4</b>	<b>SCIENTIFIC DATA CALIBRATION</b>	<b>6</b>
4.1	FLAMES – UVES Flatfield Calibrations . . . . .	6
4.1.1	Fibre Flatfield Calibration . . . . .	6
4.1.2	Slit Flatfield Calibration . . . . .	7
4.1.3	Attached Flatfield Calibrations . . . . .	8
4.2	FLAMES – UVES Wavelength Calibration . . . . .	9
4.2.1	Standard Calibrations . . . . .	9
4.2.2	Simultaneous Calibration . . . . .	10
4.3	FLAMES – UVES Pipeline Calibrations . . . . .	10
4.3.1	Order Definition (with Simultaneous Fibre) . . . . .	10
4.3.2	Format Check (Simultaneous Fibre) . . . . .	11
4.4	FLAMES – UVES Detector Calibration . . . . .	11
4.4.1	Bias frames . . . . .	11
4.4.2	Dark frames . . . . .	12
4.5	FLAMES – GIRAFFE Flatfield Calibration . . . . .	13
4.5.1	Standard Flatfield Calibration . . . . .	13
4.5.2	Attached Flatfield Calibrations . . . . .	14
4.6	FLAMES – GIRAFFE Wavelength Calibration . . . . .	15
4.6.1	Standard Calibrations . . . . .	15
4.6.2	Simultaneous Calibrations . . . . .	16
4.7	FLAMES – GIRAFFE Detector Calibration . . . . .	16
4.7.1	Bias frames . . . . .	16
4.7.2	Dark frames . . . . .	17
4.8	FLAMES – GIRAFFE Flux Calibration . . . . .	17
4.8.1	IFU and ARGUS flux standards . . . . .	17
4.9	Summary: Science Data Calibrations . . . . .	19
<b>5</b>	<b>INSTRUMENT MONITORING</b>	<b>21</b>
5.1	FLAMES – UVES Fibre Transmission Characterisation . . . . .	21
5.2	FLAMES – UVES Fibre Projector Stability Monitoring . . . . .	21
5.3	FLAMES – UVES Simultaneous Calibration Fibre Intensity Monitoring . . . . .	22
5.4	FLAMES – UVES Resolving Power Monitoring . . . . .	23

5.5	FLAMES – UVES CCD Characterisation . . . . .	23
5.6	FLAMES – UVES CCD Shutter Performance . . . . .	24
5.7	FLAMES – UVES Instrument throughput / ETC Verification . . . . .	25
5.8	FLAMES – UVES Radial Velocity Accuracy Characterisation . . . . .	25
5.9	FLAMES – UVES Motor Currents . . . . .	26
5.10	FLAMES – GIRAFFE Fibre Transmission Characterisation . . . . .	27
5.11	FLAMES – GIRAFFE Spectrograph Stability Monitoring . . . . .	27
5.12	FLAMES – GIRAFFE Simultaneous Calibration Lamp Intensity Monitoring . . . . .	28
5.13	FLAMES – GIRAFFE Resolving Power Monitoring . . . . .	28
5.14	FLAMES – GIRAFFE Spatial Resolution Monitoring . . . . .	29
5.15	FLAMES – GIRAFFE Spectrograph Focus Monitoring . . . . .	30
5.16	FLAMES – GIRAFFE CCD Characterisation . . . . .	30
5.17	FLAMES – GIRAFFE CCD Shutter Performance . . . . .	31
5.18	FLAMES – GIRAFFE Instrument throughput / ETC Verification . . . . .	32
5.18.1	FLAMES – GIRAFFE + MEDUSA rasters . . . . .	32
5.18.2	FLAMES – GIRAFFE + IFU pointings . . . . .	32
5.19	FLAMES – GIRAFFE Radial Velocity Accuracy Characterisation . . . . .	33
5.20	FLAMES – GIRAFFE Motor Currents . . . . .	34
5.21	FLAMES – OZPOZ Astrometric Model Verification . . . . .	35
5.21.1	FLAMES – GIRAFFE + MEDUSA rasters . . . . .	35
5.21.2	FLAMES – GIRAFFE + IFU pointings . . . . .	35
5.22	FLAMES – OZPOZ Fibre Configuration Performance . . . . .	36
5.23	FLAMES – OZPOZ FACB Sensitivity . . . . .	36
5.24	Summary: Instrument Monitoring . . . . .	38
<b>A</b>	<b>Calibration Time Estimates</b>	<b>40</b>
A.0.1	GIRAFFE robot calibrations . . . . .	40
A.0.2	UVES robot calibrations . . . . .	40
A.0.3	FLAMES attached flatfields . . . . .	40
<b>B</b>	<b>calobBuild configuration files</b>	<b>42</b>

# 1 Glossary

**Acquisition:** Accurate positioning of the telescope in order to centre the target on the spectrograph slit.

**BIAS frame:** Read-out of the CCD detector of zero integration time with shutter closed. The registered number of electrons per pixel has to be subtracted from a science exposure, because these were not created by photons from the source.

**Calibration:** Procedures to remove the instrumental signature from the scientific data (e.g. by subtracting BIAS frames and by dividing through by the flatfield).

**Day/Nighttime Calibrations:** Usually calibrations are done during daytime following the night of observations (“Daytime Calibrations”). This invokes a typical time delay between Science observations and Daytime calibrations of a few hours. Upon request, Nighttime Calibration can be provided in form of so-called “Attached Calibrations” for high-precision observations. Their execution time is charged to the time allocation of the science program. In the blue such flatfield calibrations can be very long and only provide enough counts to trace the fibres and not to flatfield the data.

**Flatfield:** Spectrum obtained from light source with a flat (i.e. without spectral features) energy distribution, e.g. a tungsten lamp. The registered signal provides information about the response of the detector, allowing a determination of the variation in sensitivity from pixel to pixel, the echelle order shape, the presence of bad columns on the detector, etc.

**Observation Block:** A logical unit of exposures needed to obtain a coherent set of data. Encompasses all relevant information for a successful data acquisition on a target. It consists of target information, a set of templates, parameter files for the templates, conditions, requirements and comments concerning the specified observations. It represents the entity the short-term scheduler deals with. Constructing Observation Blocks is part of the Phase II Proposal Preparation Process.

**Standard Setting:** A pre-defined setting of the instrument facilitating the preparation of the observations. The Observatory provides the relevant calibration files when a Standard Setting is used. Standard Settings for FLAMES are defined in the User’s Manual [1].

**Template** A set of instructions for the performance of a standard operation on an instrument, the instrument and detector setups. The templates represent specially devised sequences for often used instrument operations and calibrations.

**Template Signature File:** This is a description of a Template and its parameters. It contains information about the type and allowed ranges of the parameters; some of the parameters have to be set by the observer.

**Wavelength calibration:** Spectrum obtained from an emission-line source. The wavelengths of the (many) emission lines are accurately known and are used to transform pixel space into wavelength space.

## **2 List of acronyms and abbreviations**

<b>AT</b>	Acquisition Template
<b>CT</b>	Calibration Template
<b>OB</b>	Observation Block
<b>OS</b>	Observation Software
<b>OT</b>	Observation Template
<b>P2PP</b>	Phase II Proposal Preparation



## 3 Introduction

### 3.1 Overall description of the document

This document describes the calibration procedures for the FLAMES instrument at the VLT (cf. [1]).

In general there are two possible strategies for calibrations. To calibrate *science data* requires a set of calibrations, taken in due time, covering the specific instrument setup used in the science observation. To calibrate the *instrument* requires a large set of calibrations covering all offered setups but at a lower rate. In practice, for instruments like UVES and GIRAFFE which offer many standard setups, both strategies are compromised. The science data are calibrated during daytime after acquisition. In addition, a selected set of calibrations is regularly (typically daily) measured for the purpose of instrument “health checks”.

For each calibration task this document defines the:

- **Responsible** group to carry out the calibrations,
- **Phase**, i.e., when the calibrations have to be carried out (day or nighttime),
- **Frequency**, i.e., how often the calibration task has to be carried out; expressed in  $1/N$  days,
- **Purpose** of this calibration task,
- **Procedure**, i.e., the way how the calibration task is carried out,
- **Outputs**, i.e., the Pipeline data products, the Quality Control (QC) parameters, and/or the keywords entered into the VLT engineering data stream (“FITSLOG”) produced by the calibration task,
- **Prepared OBs**, i.e., the pre-prepared (impex) OBs to carry out the task (and the corresponding **OT queues** where they exist). Note that due to changes in lamp brightness then the **exposure times in these OBs may not be correct**. The exposure times are properly set from a table on the instrument workstation that is used by the calobBuild script.
- **Prepared Templates**, i.e., templates to carry out the task (if not composed in a OB)
- **Pipeline Support**, i.e., if and what support is given by the data reduction pipeline for the calibration task,
- **Duration**, i.e., an estimate of the required time to execute the calibration task,
- **Prerequisites**, i.e., possible dependencies on instrumental or sky conditions or other calibration tasks are given.

Tasks which still need implementation on the level of e.g. OB preparation, pipeline support, etc., are marked with the “under construction” logo on the page margin.

In the appendix of the document an estimate of the expected typical daily calibration times of FLAMES is given.

The technical details of the automatic execution of the daily calibration plan is implemented on Paranal in the configuration files of the automatic calibration OB tool (cmm modules `calob`, `flocal`, and `uvocal`) (cf. [2]). Therefore the main configuration files are shown in the appendix of this document.

### 3.2 Note on frequency of calibrations / validity times

Because GIRAFFE does not have a cross disperser and is not temperature controlled, there can be small shifts in the position of the fibres in the axis perpendicular to the dispersion due to temperature variations between when the observations were taken (night-time) and when the calibrations were taken (generally in the daytime). For this reason the frequency/validity interval of most calibrations is set at one day in order to minimise the temperature difference. The FITS keyword "INS.TEMP53" shows the temperature at which the science data or calibration was taken with the shift as a function in temperature for both gratings can be found on the following webpage:

[www.eso.org/observing/dfo/quality/GIRAFFE/reports/HEALTH  
/trend\\_report\\_STABILITY\\_HC.html](http://www.eso.org/observing/dfo/quality/GIRAFFE/reports/HEALTH/trend_report_STABILITY_HC.html)

Note that tests have shown that at least for Medusa then **if accurate wavelength calibration is not required** then calibrations taken further away in time can provide good results although in general this is not recommended. See the GIRAFFE reduction cookbook for details.

## References

- [1] *FLAMES User Manual*, VLT-MAN-ESO-13700-2994, Version 85, 28/08/09, A. Kaufer et al.
- [2] *Calibration OB Tool User Manual*, VLT-MAN-ESO-17240-2264, Version 1.1, 15/09/00, R. Schmutzer
- [3] *UVES Calibration Plan*, VLT-MAN-ESO-13200-1123, Issue 85, 28/08/2009, A. Kaufer et al.

## 4 SCIENTIFIC DATA CALIBRATION

This section of the FLAMES calibration plan describes which FLAMES calibration data has to be collected with which frequency to allow one to

### REMOVE INSTRUMENTAL SIGNATURES

from the scientific data.

If possible/applicable, an estimate for the accuracy of the calibration products is given.

### 4.1 FLAMES – UVES Flatfield Calibrations

#### 4.1.1 Fibre Flatfield Calibration

Responsible: Science Operations

Phase: Daytime

Frequency: In Service Mode 1 / 1 days per plate, fibre mode (8, 7+1, 6), and wavelength setting used in science data

Purpose: Provide high SNR flatfield exposures (exposure level 20000 ADU) for the purpose of

- correction of pixel-to-pixel sensitivity variations,
- determination of relative fibre-to-fibre transmission,
- fibre localisation,
- fibre spatial PSF modeling,
- echelle blaze correction.

Procedure: 1 Halogen lamp spectrum per standard wavelength setting, fibre mode and plate is taken with a level of 20000 ADU on all UVES fibres.

The UVES fibre buttons are placed on the plate in a spiral. While the CCD shutter is open, the robot sweeps over the fibres with a fibre projector fed by a tungsten lamp. The illumination level is determined by the number of sweeps over the fibre. The exposure time is determined by the number of sweeps to achieve the required intensity levels.

The flatfields of the UVES fibres are split in three different exposures distinguished by the respective UVES fibres placed on the spiral. The sequence is ODD - EVEN - ALL. The ODD and EVEN exposures are used to determine the spatial profile of the individual UVES fibres, while ALL fibres measures the relative throughput of the fibres.

Outputs: pipeline products:

- master flatfield
- fibre-order table

QC parameters:

from fibre-order table:

- number of orders found; order\_min, order\_max
- number of fibres analyzed
- residuals: mean, rms
- shifts against physical model

from fibre efficiency products:

- relative transmission per fibre (averaged across orders)

Prepared OBs: `impex/FLAMES/DaytimeCalibration/FLAMES_uves_plate<plate>_flat.obx`  
with `<plate> = 1, 2`

Pipeline Support: needed:  
`flames_cal_prep_sff_ofpos`

Duration:

Prerequisites:

See also:

#### 4.1.2 Slit Flatfield Calibration

Responsible: Science Operations

Phase: Daytime

Frequency: Daily in VM. In Service Mode 1 / 7 days per wavelength setting used in science data

Purpose: Provide high SNR slit flatfield exposures to determine the CCD's pixel-to-pixel sensitivity variations independent of the fibre flatfields described in 4.1.1 and to determine the structure of the slit noise.

Procedure: For UVES, 3 long slit halogen lamp spectra per standard wavelength setting are taken with a level of 20000 ADU at 3 different slit positions. A slit width of 1 arsec is used, the slit is shifted by  $-4\ 0\ +4$  arsec along its long side between the three exposures to cover all possible fibres.

These slit flatfields are taken with the UVES internal calibration unit and the UVES red slit. The same slit flatfields are used for the calibration of plate 1 and plate 2 fibre spectra.

Outputs: pipeline products:

- high SNR master slit flatfields (exposure level  $2 \times (3 \times 20000)$  ADU in the overlapping regions of the shifted spectra)

QC parameters:

from master slit flats:

- lamp efficiency
- slit noise (amplitude)
- fixed-pattern noise (amplitude)
- fringing amplitude (860 only)
- effective slit height

Prepared OBs: `impex/FLAMES/DaytimeCalibration/FLAMES_uves_sflat.obx`

Pipeline Support: needed:

`flames_cal_mkmaster`

Duration:

Prerequisites: Availability of UVES preslit calibration system.

See also:

### 4.1.3 Attached Flatfield Calibrations

Responsible: Science Operations: Instrument Operator

Phase: Nighttime

Frequency:

SM: FLAMES-UVES. On request. If very accurate measurement of the fibre-to-fibre transmission or fringing is required. Attached flats (normally 3) need to be added to the end of the science OB and the time accounted.

Purpose: Provide high SNR flatfields (exposure level 20000 ADU) for the purpose of accurate determination of fibre-to-fibre transmission, correction of pixel-to-pixel sensitivity variations.

For FLAMES-UVES the robot flatfields taken in the daytime are sufficient in the majority of cases.

Procedure: Halogen lamp spectra can be attached as a calibration template to the science OB which allows one to take a Nasmyth screen flatfield calibration exposure in exactly the same fibre/plate and instrument configuration as used in the science exposure.

However, the telescope is moved to zenith to allow to close the Nasmyth shutter which is used as the Nasmyth screen. The rotator is stopped at the position at the end of the science exposure.

Outputs: as in [4.1.1](#)

Templates: `FLAMES_uves_cal_flatatt.tsf`

`FLAMES_comb_cal_flatatt.tsf`

Pipeline Support: needed:

`flames_fibre_order_tables`

Duration: A few minutes per flatfield in 520, 580 and 860-nm settings.

Prerequisites:

See also:

## 4.2 FLAMES – UVES Wavelength Calibration

### 4.2.1 Standard Calibrations

Responsible: Science Operations

Phase: Daytime

Frequency: Daily per plate, fibre mode (8, 7+1, 6) and wavelength setting used in science data.

Purpose: Acquire Thorium-Argon emission-line lamp spectra to determine

- 2D (pixel-order) dispersion solutions for each fibre,
- Resolving power for each fibre.

Procedure: Take Thorium-Argon calibration lamp spectra through the fibres:

The UVES fibre buttons are placed on the plate in a spiral. While the CCD shutter is open, the robot visits each fibre button with a fibre projector fed by a Thorium-Argon lamp. The illumination level is determined by the time the illuminator stays above each fibre. The exposure time is determined by the number of fibres to visit and the visit time per fibre.

The exposure levels have been adjusted via the visit time to similar values as used for the UVES slit wavelength calibrations.

In case of the UVES fibre configuration with the simultaneous calibration fibre (7+1), the simultaneous calibration fibre is illuminated by the simultaneous calibration ThAr lamp. Due to the neutral density filter in front of this lamp, the exposure time is set to a minimum of 300sec.

Outputs: pipeline products:

- fibre line tables

QC parameters:

from fibre-linetable:

- number of lines found per fibre and total
- minimum/maximum order number detected
- number of lines accepted per fibre and total
- mean and sigma of fit residuals
- FWHM of emission line width in X and Y direction: mean/median/sigma per fibre/all fibres
- resolving power: mean/median/sigma per fibre/all fibres

Prepared OBs: `impex/FLAMES/DaytimeCalibration/FLAMES_uves_plate<plate>_wave.obx`  
with `<plate> = 1, 2`

Pipeline Support:

Duration:

Prerequisites: needed:

`flames_cal_wavcal`

See also:

### 4.2.2 Simultaneous Calibration

Responsible: User

Phase: Nighttime

Frequency: For each science spectrum if requested (fibre mode 7+1)

Purpose: Record Thorium-Argon lamp spectra during the science exposure to provide very precise wavelength calibrations

Procedure: 1 fibre of the UVES slit, the so-called “simultaneous calibration fibre” is illuminated by a Thorium-Argon calibration lamp during the science exposure to monitor drifts of the spectrograph. This mode is only offered in combination with the standard 580 setting.

Outputs: pipeline products:

- TBD

QC parameters:

- TBD

Pipeline Support: needed: TBD

## 4.3 FLAMES – UVES Pipeline Calibrations

### 4.3.1 Order Definition (with Simultaneous Fibre)

Responsible: Science Operations

Phase: Daytime

Frequency: Daily per plate and wavelength setting used in science data.

Purpose: Record tracings of the echelle orders to define the order and interorder background positions. For the first guess of the order definitions it is sufficient to expose the simultaneous calibration fibre only from which the position of all other fibres is guessed.

Procedure: take flatfield exposures with the simultaneous calibration fibre

Outputs: pipeline products:

- order definition table (first guess)

- background table.

QC parameters:

from order guess table:

- number of orders found, order\_min, order\_max

- fit residuals: mean, rms, minimum, maximum

- number of fit positions: found and selected

Prepared OBs: `impex/FLAMES/DaytimeCalibration/FLAMES_uves_plate<plate>_ordef.obx`  
with `<plate> = 1, 2`



Pipeline Support: needed:

`flames_cal_orderpos`

Duration:

Prerequisites:

See also:

### 4.3.2 Format Check (Simultaneous Fibre)

Responsible: Science Operations

Phase: Daytime

Frequency: Daily per plate and wavelength setting used in science data.

Purpose: Record emission lines of known wavelengths to adjust the physical model of the spectrograph and to find a first guess for the dispersion solution.

Procedure: take Thorium-Argon exposures with the simultaneous calibration fibre and fit the line positions as predicted by the physical model.

Outputs: pipeline products:

- guess solution for wavelength calibration.

QC parameters:

from line guess table:

- number of lines found, selected
- minimum/maximum wavelength

Prepared OBS: `impex/FLAMES/DaytimeCalibration/FLAMES_uves_plate<plate>_fmtchk.obx`  
with `<plate> = 1, 2`

Pipeline Support: needed:

`flames_cal_predict`

Duration:

Prerequisites:

See also:

## 4.4 FLAMES – UVES Detector Calibration

### 4.4.1 Bias frames

Responsible: Science Operations

Phase: Daytime

Frequency: 1 / 1

Purpose: Create a master bias frame and determine the CCD Bias characteristics

Procedure: Take 5 bias frames for the standard CCD mode 225kHz, 1x1, low

Outputs: pipeline products:

- Master bias frame

QC parameters:

- Bias level: mean/median/rms
- Readout Noise: mean/median/rms
- structure parameters in X and Y

Prepared OBs: `impex/FLAMES/DaytimeCalibration/FLAMES_uves_bias.obx`

Pipeline Support: needed:

`uves_cal_mkmaster`

Duration:

Prerequisites:

See also: [3]

#### 4.4.2 Dark frames

Responsible: Science Operations

Phase: Daytime

Frequency: 1 / 30

Purpose: Create a master dark frame and determine the CCD dark current and the rate of cosmic hits

Procedure: Take 3 x 1 hour dark frames for the standard CCD mode 225kHz, 1x1, low

Outputs: pipeline products:

- master dark

QC parameters:

- (mean) dark current
- cosmic hit rate

Prepared OBs: `impex/UVES/Maintenance/UVES_tec_dark.obx`

Pipeline Support: needed:

`flames_cal_mkmaster`

Duration: 3 hours

Prerequisites: CCD must have been online for > 6 h, better 12 or 24 h (otherwise gradients across the CCD might be present).

See also: [3], darks with closed and open shutter (parasitic light) are taken also as part of the UVES calibration plan in 2x2 readout mode.

## 4.5 FLAMES – GIRAFFE Flatfield Calibration

### 4.5.1 Standard Flatfield Calibration

Responsible: Science Operations

Phase: Daytime

Frequency: Daily; in Service Mode 1 / 1 days per plate, fibre type, and spectrograph setting used in science data

Purpose: Provide high SNR flatfield exposures (exposure level 20000 ADU) for the purpose of

- correction of pixel-to-pixel sensitivity variations,
- determination of relative fibre-to-fibre transmission,
- fibre localisation,
- fibre spatial PSF modelling (TBC),
- echelle blaze correction.

Procedure: 3 Halogen lamp spectra per standard wavelength setting and plate are taken with a level of 20000 ADU. For blue settings (central wavelength < 400 nm) 3 times 3 exposures of a 5000 ADU level are taken not to exceed an exposure time of 300 sec per exposure.

For each fibre type the fibre buttons are placed on the plate in a spiral. While the CCD shutter is open, the robot sweeps over the fibres with a fibre projector fed by a tungsten lamp. The illumination level is determined by the number of sweeps over the fibre. The exposure time is determined by the number of sweeps to achieve the required intensity levels. The number of sweeps depends on the fibre type used and the spectrograph wavelength.

Outputs: pipeline products:

- master flatfield
- localization master

QC parameters:

from master flat:

- fixed-pattern noise (across fibres)
- relative transmission: mean/rms
- absolute transmission per fibre (averaged across order, as counts per sec)

from localization master:

- fibre positions (relative distance, inclination against Y)
- fibre PSF (mean/rms)

Prepared OBs: `impex/FLAMES/DaytimeCalibration/FLAMES_giraf_<mode><plate>_HR_flat.obx`  
`impex/FLAMES/DaytimeCalibration/FLAMES_giraf_<mode><plate>_LR_flat.obx`

with <mode> = medusa, ifu and <plate> = 1, 2 or

with <mode> = argus and <plate> = 2

Pipeline Support: needed:

[locMast]

Duration:

Prerequisites:

See also:

#### 4.5.2 Attached Flatfield Calibrations

Responsible: Science Operations: Instrument Operator

Phase: Nighttime

Frequency:

SM: Medusa. On request. If very accurate measurement of the fibre-to-fibre transmission is required. Attached flats (normally 3) need to be added to the end of the science OB and the time accounted.

SM: Argus or IFU. Daily. Three flatfields taken by the observatory (normally in twilight, daily) in the same setting as the science although in IFU with the position not the same on the plate as the science observation. Generally a standard star observation is taken before the attached flatfields in order to setup the instrument and place the IFUs in a circle with one on the standard star.

VM: Argus or IFU. Daily. Three attached flatfields are taken normally in twilight for each setting used.

Purpose: Provide high SNR flatfields (exposure level 20000 ADU) for the purpose of accurate determination of fibre-to-fibre transmission, correction of pixel-to-pixel sensitivity variations.

For Medusa the robot flatfields taken during the daytime are sufficient in the majority of cases.

For ARGUS three attached flatfields are necessary as the illumination pattern of the screen flats is much better than the normal robot flatfields. Hence they are taken as part of the calibration plan ideally on the same night as the observations.

For IFU three attached flatfields are desirable as the illumination pattern of the screen flats is somewhat better than the normal robot flatfields. Hence they are taken as part of the calibration plan ideally on the same night as the observations.

Procedure: Halogen lamp spectra can be attached as a calibration template to the science OB which allows one to take a Nasmyth screen flatfield calibration exposure in exactly the same fibre/plate and instrument configuration as used in the science exposure.

However, the telescope is moved to the zenith to allow to close the Nasmyth shutter which is used as the Nasmyth screen. The rotator is stopped at the position at the end of the science exposure.

Outputs: pipeline products:

as in 4.5.1

QC parameters:

as in 4.5.1

Templates: FLAMES\_giraf\_cal\_flatatt.tsf  
FLAMES\_comb\_cal\_flatatt.tsf

Pipeline Support: needed; as in 4.5.1

o flatfield the data.

Prerequisites:

See also:

## 4.6 FLAMES – GIRAFFE Wavelength Calibration

### 4.6.1 Standard Calibrations

Responsible: Science Operations

Phase: Daytime

Frequency: Daily per plate, fibre type, and spectrograph setting used in science data.

Purpose: Acquire Thorium-Argon emission-line lamp spectra to determine

- 2D (pixel-order) dispersion solutions for each fibre,
- Resolving power for each fibre,
- slit geometry for each slit.

Procedure: take Thorium-Argon calibration lamp spectra through the fibres:

For each fibre type the fibre buttons are placed on the plate in a spiral. While the CCD shutter is open, the robot sweeps over the fibres with a fibre projector fed by a Thorium-Argon lamp. The illumination level is determined by the number of sweeps over the fibre. The exposure time is determined by the number of sweeps to achieve the required intensity levels. The number of sweep is highly dependent on the fibre type used and the spectrograph wavelength.

Outputs: pipeline products:

- dispersion coefficients, line table

QC parameters:

from the line table:

- mean and rms of residuals
- dispersion coefficients
- number of lines found/used
- resolving power (also 6.10): mean/median/rms (averaged and per fibre)
- line width in X (also 6.11) and Y: mean/median/rms (averaged and per fibre)

Prepared OBs: `impex/FLAMES/DaytimeCalibration/FLAMES_giraf_<mode><plate>_HR_wave.obx`  
`impex/FLAMES/DaytimeCalibration/FLAMES_giraf_<mode><plate>_LR_wave.obx`

with `<mode>` = medusa, ifu and `<plate>` = 1, 2 or

with `<mode>` = argus and `<plate>` = 2

Pipeline Support: needed:

[extract, wcal]

Duration:

Prerequisites:

See also:

### 4.6.2 Simultaneous Calibrations

Responsible: User

Phase: Nighttime

Frequency: For each science spectrum if requested (SIMFLAG “ON”)

Purpose: Record Thorium-Argon lamp spectra during the science exposure to provide very precise wavelength calibrations

Procedure: 5 fibres in each Giraffe slit, the so-called “simultaneous calibration fibres” are illuminated by a Thorium-Argon calibration lamp during the science exposure to monitor drifts of the spectrograph.

Outputs: pipeline products:

- accurate radial velocities.

QC parameters:

as in 4.6.1 plus:

- second order correction of dispersion coefficients

Pipeline Support: needed

Comments: For settings redward of 650-nm very strong Argon lines cause contamination.

## 4.7 FLAMES – GIRAFFE Detector Calibration

### 4.7.1 Bias frames

Responsible: Science Operations

Phase: Daytime

Frequency: 1 / 1

Purpose: Create a master bias frame and determine the CCD Bias characteristics

Procedure: Take 5 bias frames for the standard CCD mode 225kHz, 1x1, low

Outputs: pipeline products:

- Master bias frame

QC parameters:

- Bias level: mean/median/rms
- Readout Noise: mean/median/rms
- structure parameters in X and Y

Prepared OBs: `impex/FLAMES/DaytimeCalibration/FLAMES_giraffe_bias.obx`

Pipeline Support: needed:  
[biasMast]

Duration:

Prerequisites:

See also:

#### 4.7.2 Dark frames

Responsible: Science Operations

Phase: Daytime

Frequency: 1 / 30

Purpose: Create a master dark frame and determine the CCD dark current and the rate of cosmic hits

Procedure: Take 3 x 1 hour dark frames for the standard CCD mode 225kHz, 1x1, low

Outputs: pipeline products:

- master dark
- QC parameters:
- (mean) dark current
- cosmic hit rate

Prepared OBs: `impex/FLAMES/DaytimeCalibration/FLAMES_giraffe_dark.obx`

Pipeline Support: needed:  
[biasMast]

Duration: 3 hours

Prerequisites: CCD must have been online for > 6 h, better 12 or 24 h (otherwise gradients across the CCD might be present).

See also:

## 4.8 FLAMES – GIRAFFE Flux Calibration

### 4.8.1 IFU and ARGUS flux standards

Responsible: Science Operations: Instrument Operator

Phase: Nighttime / Twilight

## Frequency:

VM: once per run, plate and spectrograph settings used in science data. Three attached flatfields should also be taken. Note that the attached flatfields have a validity interval of one day.

SM: Within 7 days of the observation being taken. Three attached flatfields will also be taken. Note that the attached flatfields have a validity interval of one day.

Purpose: Measure the response function to allow flux calibration of the science data.

Procedure: Observe spectrophotometric standard stars with IFUs and/or ARGUS plus an attached flatfield.

For IFUs, only one IFU will be assigned to the spectrophotometric standard star. The other IFUs and the IFU sky fibres will be placed in a circle of the same radius to be illuminated after the standard star observation via the Nasmyth screen.

For ARGUS, the spectrophotometric standard star is centred on the ARGUS IFU. The other ARGUS Sky fibres will be placed in a circle of the small radius to be illuminated after the standard star observation via the Nasmyth screen.

The attached flatfields will be used to correct for the relative transmission of the IFUs, IFU Sky fibres, and the ARGUS sky fibres. If time permits, in VM the attached flat part can be performed during the daytime or twilight.

Outputs: pipeline products:

- response function for flux calibration

QC parameters:

- response function
- efficiency curves

Prepared OBs: `impex/FLAMES/ArgusSpecPhotStd/FLAMES_argstd_1_1_<target>.obx`  
`impex/FLAMES/ArgusSpecPhotStd/FLAMES_argstd_1_1.67_<target>.obx`  
`impex/FLAMES/IfuSpecPhotStd/FLAMES_ifustd_<target>.obx`  
with `<target>` equal to the name of the specphot standard

OT queues: `FLAMES.ARGUS.SpecPhotStd`, `FLAMES.IFU.SpecPhotStd`

Pipeline Support: needed

Duration:

Prerequisites: Good astrometry on specphot standard star fields,

Spectrophotometric extinction tables for Paranal (at the moment La Silla tables are used). Flux tables for `target` (currently the Midas fluxtable is used).

See also:



## **4.9 Summary: Science Data Calibrations**

The following table provides a summary of the FLAMES-UVES and FLAMES-GIRAFFE calibration plan.

<b>FLAMES – UVES Science Data Calibration Plan</b>			
(per instrument setting: plate, fibre mode, and central wavelength)			
Calibration	num.	freq. [1/days]	purpose
Robot Flatfields	1	1 / 1	pix-to-pix sensitivity variations fibre-to-fibre transmission fibre localisation fibre PSF modelling blaze correction
Slit Flatfields	3	1 / 7	pix-to-pix sensitivity variations
Attached Fibre Flatfields	<i>n</i>	o.r.	high-precision flatfielding
Wavelength	1	1 / 1	dispersion solution resolving power
Sim. Fibre Order Definition	1	1 / 1	order and background def.
Sim. Fibre Format Check	1	1 / 1	dispersion guess solution
Bias	5	1 / 1	master biases, bias chars.
Dark	3	1 / 30	master darks, dark current, cosmic rate
<b>FLAMES – GIRAFFE Science Data Calibration Plan</b>			
(per instrument setting: plate, fibre mode, resolution and central wavelength)			
Calibration	num.	freq. [1/days]	purpose
Robot Flatfields	3	1 / 1	pix-to-pix sensitivity variations fibre-to-fibre transmission fibre(=spectra) localisation
Attached Flatfields	<i>n</i>	o.r.	high-prec. flatfielding, Medusa
Attached Flatfields	3	1 / 1	high-precision flatfielding, Argus or IFU
Wavelength	1	1 / 1	dispersion solution resolving power slit geometry
Bias	5	1 / 1	master biases, bias char.
Dark	3	1 / 30	master darks, dark curr., CRs
IFU: Flux Standard	1	1 / 7	response corr. flux calib
Attached Flats	3	1 / 1	rel. trans. IFU / Sky fibres
ARGUS: Flux Standard	1	1 / 7	response correction, flux calib
Attached Flats	3	1 / 1	rel. trans. ARGUS / Sky fibres
o.r. = on request only, corresponding OBs to be provided by user			
<i>n</i> = number to be defined by user			

## 5 INSTRUMENT MONITORING

This section of the FLAMES calibration plan describes which FLAMES system data has to be collected with which frequency to allow trend analysis of the instrument health and to initiate preventive maintenance. Furthermore, data to further characterise the instrument is taken.

### 5.1 FLAMES – UVES Fibre Transmission Characterisation

Responsible: Science Operations

Phase: Daytime

Frequency: Daily; per plate and wavelength setting

Purpose: Determine the absolute fibre transmission as function of plate, fibre number and wavelength (within the limits of the stability of the OzPoz flatfield lamp and calibration system)

Procedure: as described in [4.1.1](#)

Outputs: pipeline products:

- fibre efficiency files

QC parameters:

- absolute transmission per fibre (averaged across orders, as counts per sec)

Pipeline Support: needed: TBD

Duration:

Prerequisites:

See also:

### 5.2 FLAMES – UVES Fibre Projector Stability Monitoring

Responsible: Science Operations

Phase: Daytime

Frequency: Daily for both slits using the 580 wavelength setting

Purpose: Characterise the mechanical stability of the fibre projector. Measure the shifts of the fibre projector along (x direction) and perpendicular (y direction) to the slit

Procedure: as described in [4.3.2](#)

in addition the shift of the positions of the ThAr lines has to be measured with respect to a master reference format check frame.

the measured shift is a superposition of the shifts of the fibre projector and the shifts in the spectrograph. The latter are measured by the UVES calibration plan using slit formatchecks. Therefore, the true shifts of the fibre projector can be determined.

Outputs: pipeline products:

- QC parameters:
  - X and Y shifts against physical model and against reference frame
  - by comparison to UVES echelle trended X and Y shifts: X and Y shifts of positioner

Pipeline Support: needed

Duration:

Prerequisites:

See also:

### 5.3 FLAMES – UVES Simultaneous Calibration Fibre Intensity Monitoring

Responsible: Science Operations

Phase: Daytime

Frequency: Weekly for both slits using the 580 wavelength setting

Purpose: Monitor the intensities of the simultaneous Thorium-Argon calibration lamp to allow preventive exchange before it fails.

Procedure: as described in [4.6.1](#)

in addition the intensities of the ThAr lines in the simultaneous calibration fibres have to be measured with respect to a master reference frame; the relative intensities are computed.

Outputs: pipeline products:

- QC parameters:
  - relative line intensities as function of time

Pipeline Support: needed

Duration:

Prerequisites:

See also:

## 5.4 FLAMES – UVES Resolving Power Monitoring

Responsible: Science Operations

Phase: Daytime

Frequency: Weekly for both slits and the 520, 580, 860 wavelength settings

Purpose: Measure the average resolving power per wavelength setting

Procedure: as described in [4.3.2](#)

in addition the resolving power is measured from the ThAr lines

Outputs: pipeline products:

- 

QC parameters:

- resolving power: mean/median/sigma per fibre/all fibres
- FWHM of emission line width in X and Y direction: mean/median/sigma per fibre/all fibres

Pipeline Support: needed

Duration:

Prerequisites:

See also:

## 5.5 FLAMES – UVES CCD Characterisation

Responsible: Science Operations

Phase: Daytime

Frequency: Monthly

Purpose: Characterise the CCD via the following parameters:

- Bias level
- Gain
- RON
- Dark current
- Bad pixel/columns map
- Linearity
- Shutter error
- Relative Contamination

Procedure: Take a series of UVES CCD lamp flats, 1h darks, and biases for the standard CCD mode

225kHz, 1x1, low

Outputs: pipeline products:

- 
- QC parameters:
  - Bias level
  - Gain
  - RON
  - Dark current
  - Bad pixel/columns map
  - Linearity
  - Shutter error
  - Relative Contamination

Prepared OBS: `impex/UVES/Maintenance/UVES_red_ccdtest.obx`

OT queue: `FLAMES.Calib-All`

Pipeline Support: needed

Duration:

Prerequisites: CCD must have been online for > 6 h, better 12 or 24 h (otherwise gradients across the CCD might be present).

See also: [3]

## 5.6 FLAMES – UVES CCD Shutter Performance

Responsible: Engineering

Phase: Day- and Nighttime

Frequency: Every CCD exposure

Purpose: Monitor the performance of the UVES Red CCD shutter

Procedure: Record the opening and closing time of the CCD shutter. Tend the measured times over time. A increase in the times indicate mechanical wearout of the shutter mechanics.

Outputs: FITSLOG keywords:

DET SHUT TMOOPEN Time to open shutter [s].  
DET SHUT TMCLOS Time to close shutter [s].

Pipeline support: not needed

Prerequisites:

See also: [3]

## 5.7 FLAMES – UVES Instrument throughput / ETC Verification

Responsible: Science Operations

Phase: Nighttime

Frequency: Monthly

Purpose: Measure the instrument throughput by comparing the observed fluxes with the ETC predicted fluxes as function of wavelength

Procedure: On both plates configure and observe with a 3x3 raster of 0.4" stepsize ("jitter") in the three standard wavelength settings an astrometric field with targets of known brightness and spectral type.

Extract the measured flux at the centre of the raster as function of wavelength.

Compare the results with the ETC predictions taking into account atmospheric conditions and the airmass of the observation.

Outputs: pipeline products:

- 

QC parameters:

- 

Prepared OBs: `impex/FLAMES/Maintenance/FLAMES_uves_raster520_<field>.obx`

`impex/FLAMES/Maintenance/FLAMES_uves_raster580_<field>.obx`

`impex/FLAMES/Maintenance/FLAMES_uves_raster860_<field>.obx`

with `<field>` the name of the astrometric field. Fixed fields to cover the whole year are available.

Pipeline Support: needed

Duration:

Prerequisites: Photometric, dark sky, seeing < 1.2".

See also:

## 5.8 FLAMES – UVES Radial Velocity Accuracy Characterisation

Responsible: Science Operations

Phase: Twilight / Nighttime

Frequency: Monthly

Purpose: Determine long-term radial velocity accuracy by repeated observation of the same field.

Procedure: On both plates configure and observe in the 580 setting using the simultaneous calibration fibre an astrometric field with targets of known radial velocities.

As target field, old open clusters preferred to have low-rotation and low-activity solar type stars

Determine the radial velocities of the individual stars making use of the simultaneous calibration fibre.

Outputs: pipeline products:

- 

QC parameters:

- 

Prepared OBS: `impex/FLAMES/Maintenance/FLAMES_uves_radvel_<field>.obx`

with `<field>` the name of the astrometric field. Fixed fields to cover the whole year are available.

Pipeline Support: needed

Duration:

Prerequisites: Clear sky, no moon restrictions, seeing  $< 1.6''$ .

See also:

## 5.9 FLAMES – UVES Motor Currents

Responsible: Engineering

Phase: Daytime

Frequency: Monthly

Purpose: Detect trends in the motor currents of the different functions to allow preventive maintenance

Procedure: Record UVES motor currents over the full encoder range and both senses of motion

Outputs: FITSLOG keywords:

- Sample file,
- Min/Max/Average currents of all motorized functions

Prepared OBS: `impex/UVES/Maintenance/MotorCurTest.obx`

Pipeline Support:

Duration:

Prerequisites:

See also: [3]



## 5.10 FLAMES – GIRAFFE Fibre Transmission Characterisation

Responsible: Science Operations

Phase: Daytime

Frequency: Daily; per plate and wavelength setting

Purpose: Determine the absolute fibre transmission as function of plate, fibre number and wavelength (within the limits of the stability of the OzPoz flatfield lamp and calibration system)

Procedure: as described in [4.5.1](#)

Outputs: pipeline products:

as in [4.5.1](#)

QC parameters:

as described in [4.5.1](#) plus

- numbers for absolute transmission as function of fibre number and wavelength

Pipeline Support: needed

Duration:

Prerequisites:

See also:

## 5.11 FLAMES – GIRAFFE Spectrograph Stability Monitoring

Responsible: Science Operations

Phase: Daytime

Frequency: Daily for Argus and both IFU and MEDUSA slits using the HR9 wavelength setting

Purpose: Determine the spectral shifts along and perpendicular to the dispersion direction for all simultaneous fibres

Procedure: Take spectra with the simultaneous ThAr calibration lamp on.

Measure the shift of the positions of the ThAr lines with respect to a master reference frame for each individual simultaneous fibre spectrum; the average shifts over all fibres are computed.

Outputs: pipeline products:

- 

QC parameters:

- spectral shifts in X and Y relative to reference frames

Prepared OBs: `impex/FLAMES/Maintenance/GIRAF_tec_stability.obx`

Pipeline Support: needed

Duration: 15 min

Prerequisites:

See also:

## 5.12 FLAMES – GIRAFFE Simultaneous Calibration Lamp Intensity Monitoring

Responsible: Science Operations

Phase: Daytime

Frequency: Weekly for Argus and both IFU and MEDUSA slits using the HR9 wavelength setting

Purpose: Monitor the intensities of the simultaneous Thorium-Argon calibration lamp to allow preventive exchange before it fails.

Procedure: as described in [5.11](#)

in addition the intensities of the ThAr lines in the simultaneous calibration fibres have to be measured with respect to a master reference frame; the relative intensities are computed.

Outputs: pipeline products:

- QC parameters:
- relative line intensities as function of time

Pipeline Support: needed

Duration:

Prerequisites: as in [5.11](#)

See also:

## 5.13 FLAMES – GIRAFFE Resolving Power Monitoring

Responsible: Science Operations

Phase: Daytime

Frequency: Weekly for Argus and both IFU and MEDUSA slits using the HR2,9,14 and LR1,4,7 wavelength settings

Purpose: Determine the resolving power per wavelength setting averaged over all fibres

Procedure: Take spectra with the simultaneous ThAr calibration lamp on.

Measure the average resolving power for each individual fibre spectrum; the average resolution over all fibres per wavelength setting is computed.

Outputs: pipeline products:

- 
- QC parameters:
- Resolving power as function of temperature

Prepared OBs: `impex/FLAMES/Maintenance/GIRAF_tec_resolution.obx`

Pipeline Support: needed

Duration: 60 min

Prerequisites:

See also:

## 5.14 FLAMES – GIRAFFE Spatial Resolution Monitoring

Responsible: Science Operations

Phase: Daytime

Frequency: Weekly for Argus and both IFU and MEDUSA slits using the HR2,9,14 and LR1,4,7 wavelength settings

Purpose: Determine the spatial resolution (i.e., the width of the spectra perpendicular to the dispersion direction) per wavelength setting averaged over all simultaneous fibres

Procedure: as described in [5.13](#)

in addition the average spatial resolution is measured for each individual fibre spectrum; the average resolution over all fibres per wavelength setting is computed.

Outputs: pipeline products:

- 
- QC parameters:
- Spatial Resolution power as function of temperature
- Spatial Resolution versus Resolving power

Pipeline Support: needed

Duration: as in [5.13](#)

Prerequisites:

See also:

## 5.15 FLAMES – GIRAFFE Spectrograph Focus Monitoring

Responsible: Science Operations

Phase: Daytime

Frequency: Bi-monthly for Argus and both IFU and MEDUSA slits using the HR2,9,14 and LR1,4,7 wavelength settings

Purpose: Determine the slit focus value for different slits and wavelength settings for the temperature under which the test was carried out

Procedure: Take spectra with the simultaneous ThAr calibration lamp on. Measure the FWHM of the simultaneous ThAr lines and determine the best focus value.

Outputs: pipeline products:

- 
- QC parameters:
  - focus value as function of slit, wavelength setting, and temperature

Prepared OBs: `impex/FLAMES/Maintenance/GIRAF_tec_focus.obx`

Pipeline Support: needed

Duration: 3 hrs

Prerequisites:

See also:

## 5.16 FLAMES – GIRAFFE CCD Characterisation

Responsible: Science Operations

Phase: Daytime

Frequency: Monthly

Purpose: Characterise the CCD via the following parameters:

- Bias level
- Gain
- RON
- Dark current
- Bad pixel/columns map
- Linearity
- Shutter error
- Relative Contamination

Procedure: Take a series of GIRAFFE CCD lamp flats, 1h darks, and biases for the standard CCD mode

225kHz, 1x1, low

Outputs: pipeline products:

- 
- QC parameters:
  - Bias level
  - Gain
  - RON
  - Dark current
  - Bad pixel/columns map
  - Linearity
  - Shutter error
  - Relative Contamination

Prepared OBs: `impex/FLAMES/Maintenance/GIRAF_tec_ccdtest.obx`  
`impex/FLAMES/Maintenance/GIRAF_tec_dark.obx`

OT queue: FLAMES.Calib-All

Pipeline Support: needed

Duration: 1 hr + 3 hrs for darks

Prerequisites: CCD must have been online for > 6 h, better 12 or 24 h (otherwise gradients across the CCD might be present).

See also:

## 5.17 FLAMES – GIRAFFE CCD Shutter Performance

Responsible: Engineering

Phase: Day- and Nighttime

Frequency: Every CCD exposure

Purpose: Monitor the performance of the GIRAFFE CCD shutter

Procedure: Record the opening and closing time of the CCD shutter. Tend the measured times over time. A increase in the times indicate mechanical wearout of the shutter mechanics.

Outputs: FITSLOG keywords:

DET SHUT TMOPEX Time to open shutter [s].  
DET SHUT TMCLOS Time to close shutter [s].

Pipeline support: not needed

Prerequisites:

See also:

## 5.18 FLAMES – GIRAFFE Instrument throughput / ETC Verification

### 5.18.1 FLAMES – GIRAFFE + MEDUSA rasters

Responsible: Science Operations

Phase: Nighttime

Frequency: Monthly

Purpose: Measure the instrument throughput by comparing the observed fluxes with the ETC predicted fluxes as function of wavelength

Procedure: On both plates configure and observe with a 3x3 raster of 0.4" stepsize in the L1, L4, L8 wavelength settings an astrometric field with targets of known brightness and spectral type.

Extract the measured flux at the centre of the raster as function of wavelength.

Compare the results with the ETC predictions taking into account atmospheric conditions and the airmass of the observation.

Outputs: pipeline products:

- 
- QC parameters:
- 

Prepared OBs: `impex/FLAMES/Maintenance/FLAMES_giraf_rasterL1_<field>.obx`  
`impex/FLAMES/Maintenance/FLAMES_giraf_rasterL4_<field>.obx`  
`impex/FLAMES/Maintenance/FLAMES_giraf_rasterL8_<field>.obx`

with <field> the name of the astrometric field. Fixed fields to cover the whole year are available.

Duration:

Prerequisites: Photometric, dark sky, seeing < 1.2".

See also:

### 5.18.2 FLAMES – GIRAFFE + IFU pointings

Responsible: Science Operations

Phase: Nighttime

Frequency: Monthly

Purpose: Measure the instrument throughput by comparing the observed fluxes with the ETC predicted fluxes as function of wavelength

Procedure: On both plates configure and observe with IFUs in the L1, L4, L8 wavelength settings an astrometric field with stars of known brightness and spectral type  
reconstruct the stellar images from the IFU spectra  
measure the total flux for each target  
Compare the results with the ETC predictions taking into account atmospheric conditions and the airmass of the observation.

Outputs: pipeline products:

- 
- QC parameters:
- 

Prepared OBs: `impex/FLAMES/Maintenance/FLAMES_giraf_ifuL1_<field>.obx`  
`impex/FLAMES/Maintenance/FLAMES_giraf_ifuL4_<field>.obx`  
`impex/FLAMES/Maintenance/FLAMES_giraf_ifuL8_<field>.obx`

with `<field>` the name of the astrometric field. Fixed fields to cover the whole year are available.

Pipeline Support: needed

Duration:

Prerequisites: Photometric, dark sky, seeing  $< 1.8''$ .

See also:

## 5.19 FLAMES – GIRAFFE Radial Velocity Accuracy Characterisation

Responsible: Science Operations

Phase: Twilight / Nighttime

Frequency: Monthly

Purpose: Determine long-term radial velocity accuracy by repeated observation of the same field.

Procedure: On both plates configure and observe in the H10 setting using the simultaneous calibration fibre an astrometric field with targets of known radial velocities.

Determine the radial velocities of the individual stars making use of the simultaneous calibration fibre.

Outputs: pipeline products:

- 
- QC parameters:
- RV precision: mean/rms

Prepared OBs: `impex/FLAMES/Maintenance/FLAMES_giraf_radvel_<field>.obx`

with `<field>` the name of the astrometric field. Fixed fields to cover the whole year are available.

Pipeline Support: needed

Duration:

Prerequisites: Clear sky, no moon restrictions, seeing  $< 1.6''$ .

See also:

## 5.20 FLAMES – GIRAFFE Motor Currents

Responsible: Engineering

Phase: Daytime

Frequency: Monthly

Purpose: Detect trends in the motor currents of the different functions to allow preventive maintenance

Procedure: Record GIRAFFE motor currents over the full encoder range and both senses of motion

Outputs: FITSLOG keywords:

- Sample file,
- Min/Max/Average currents of all motorized functions

Prepared OBs: `impex/FLAMES/Maintenance/GIRAF_tec_motorcurr.obx`

Pipeline Support: none

Duration: 30 min

Prerequisites:

See also:



## 5.21 FLAMES – OZPOZ Astrometric Model Verification

### 5.21.1 FLAMES – GIRAFFE + MEDUSA rasters

Responsible: Science Operations

Phase: Nighttime

Frequency: Monthly

Purpose: Check the accuracy of the astrometric model

Procedure: take data as described in [5.18.1](#)

reconstruct the stellar images from the raster  
determine the RA and DEC centroid of the stars  
determine the RA and DEC offsets w.r.t. the nominal positions  
fit an astrometric model to the offsets

Outputs: pipeline products:

- 
- QC parameters:
- new model parameters:
  - centre plate RA offset
  - centre plate DEC offset
  - scale change
  - additional rotation

Pipeline Support:

Duration:

Prerequisites:

See also:

### 5.21.2 FLAMES – GIRAFFE + IFU pointings

Responsible: Science Operations

Phase: Nighttime

Frequency: Monthly

Purpose: Check the accuracy of the astrometric model

Procedure: take data as described in [5.18.2](#)

reconstruct the stellar images from the IFU spectra  
determine the RA and DEC centroid of the stars  
determine the RA and DEC offsets w.r.t. the nominal positions  
fit an astrometric model to the offsets

Outputs: pipeline products:

- 
- QC parameters:
- new model parameters:
  - centre plate RA offset
  - centre plate DEC offset
  - scale change
  - additional rotation

Pipeline Support: needed

Duration:

Prerequisites:

See also:

## 5.22 FLAMES – OZPOZ Fibre Configuration Performance

Responsible: Science Operations

Phase: Day- and Nighttime

Frequency: N/A

Purpose: Monitor the performance of the fibre positioner

Procedure: At the end of any fibre configuration performance parameters are recorded.

Outputs: FITSLOG keywords:

INS PCC TIMTOT	Total configuration time [s].
INS PCC NUMMOVE	Number of moves in the configuration.
INS PCC NUMFIB	Number of fibres in the configuration.
INS PCC MPERF	Average number of moves per fibre.
INS PCC TIMFIB	Average time per fibre in configuration [s].
INS PCC TIMMOVE	Average time per move in configuration [s].
INS PCC PPERM	Average number of placements per move.

Pipeline support: not needed

Prerequisites:

See also:

## 5.23 FLAMES – OZPOZ FACB Sensitivity

Responsible: Science Operations

Phase: Nighttime

Frequency: 1 / 90

Purpose: Monitor the sensitivity of the FACBs

Procedure: Observe with FACBs fiducial stars of known magnitude and determine countrates for gives magnitude.

Every time a FACB image is saved, the brightness of the stars is determined and logged together with the magnitude of the stars to the FITSLOG.

The countrate then is scaled to a magnitude of 15.

Outputs: FITSLOG keywords:

INS FACBi CNTS FACB countrate [ADU/sec]

INS FACBi MAG FACB R magnitude [mag]

INS FACBi SENS FACB sensitivity [ADU/sec @ 15mag]

Pipeline support: not needed

Prerequisites:

See also:

## **5.24 Summary: Instrument Monitoring**

Monitoring data to be made available as QC parameters through QC webpages and FITSLOG keywords through the Paranal Autrep database with standard plots created on a daily basis. The data for the following instrument monitoring tasks might already be available from the science data calibrations.

Some of the monitoring tasks are already covered by the UVES calibration plan.

**FLAMES – UVES Instrument Monitoring Plan**

Calibration	number	freq [1/days]	purpose
Fibre Flatfields	3	1 / 1	absolute fibre transmission
Sim. Fibre Format Check	1	1 / 1	fibre projector stability
		1 / 7	resolving power monitoring
		1 / 1	sim. ThAr lamp intensity
CCD flats + biases	<i>seq</i>	1 / 30	CCD characterization CCD contamination
UVES rasters on astrometric fields	3x3xv	1 / 30	instrument throughput / ETC verification
RV Standard field	1	1 / 30	long-term RV accuracy

**FLAMES – GIRAFFE Instrument Monitoring Plan**

Calibration	number	freq [1/days]	purpose
Flatfields	1	1 / 1	absolute fibre transmission
Wavelength	1	1 / 1	spectrograph stability
		1 / 7	resolving power monitoring
		1 / 7	spatial resolution monitoring
		1 / 1	sim. ThAr lamp intensity
CCD flats + biases	<i>seq</i>	1 / 30	CCD characterization CCD contamination
ARGUS standard star	1	1 / 30	instrument throughput / ETC verification
IFU standard star	1	1 / 30	instrument throughput / ETC verification
RV standard field	1	1 / 30	long-term RV accuracy

**FLAMES – OZPOZ Instrument Monitoring Plan**

Calibration	number	freq [1/days]	purpose
MEDUSA rasters on astrometric fields	3x3xw	1 / 365	verif. of astrometric model
IFU pointings on astrometric fields	1xw	1 / 365	verif. of astrometric model
Any fibre configuration			fibre conf. performance
FACB images		1 / 90	FACB sensitivity

$v = 3$  = number of wavelength settings := 520, 580, 860

$w = 3$  = number of wavelength settings := LR1, LR4, LR8

*seq* = special sequence: 5 biases + 10 flatfield pairs of equal exposure time covering the dynamic range

## A Calibration Time Estimates

Table 1 shows the integration times used for robot and attached flatfield calibrations. To these must be added the approximate configuration times. For the GIRAFFE configurations, once the fibres have been placed on the plate, re-configuration for different wavelengths is not necessary. **Note that in the blue the attached flatfield times are long** and do not provide enough counts to flatfield accurately.

### A.0.1 GIRAFFE robot calibrations

Calibration times assuming a clean plate to begin with.

MEDUSA spiral configuration: 20-minutes

IFU spiral configuration: 5-minutes.

ARGUS configuration: 1-minute. The ARGUS robot-flatfields have much less good illumination than ARGUS attached screen flats so the latter should ideally be taken within one day of the science observation due to temperature shifts in the instrument.

### A.0.2 UVES robot calibrations

UVES spiral configuration: 5 minutes.

### A.0.3 FLAMES attached flatfields

Mode	p2pp name	ETC name	$t(\text{arc,robot})$	$t(\text{FF,robot})$	$t(\text{FF,screen})$
Medusa	379.0	HR1	600	1250.0	5000
Medusa	395.8	HR2	600	200.0	600
Medusa	412.4	HR3	600	235.3	600
Medusa	429.7	HR4	600	83.0	200
Medusa	447.1A	HR5A	600	80.0	150
Medusa	447.1B	HR5B	600	80.0	300
Medusa	465.6	HR6	600	26.3	100
Medusa	484.5A	HR7A	600	30.3	50
Medusa	484.5B	HR7B	600	30.3	140
Medusa	504.8	HR8	600	12.5	30
Medusa	525.8A	HR9A	600	16.7	60
Medusa	525.8B	HR9B	600	16.7	80
Medusa	548.8	HR10	600	5.3	25
Medusa	572.8	HR11	600	6.7	30
Medusa	599.3	HR12	600	3.2	15
Medusa	627.3	HR13	600	3.8	20
Medusa	651.5A	HR14A	600	6.1	11
Medusa	651.5B	HR14B	600	6.1	25
Medusa	665.0	HR15N	600	6.1	10
Medusa	679.7	HR15	600	3.2	10
Medusa	710.5	HR16	600	3.8	10
Medusa	737.0A	HR17A	600	10.0	6
Medusa	737.0B	HR17B	600	10.0	22
Medusa	769.1	HR18	600	6.2	7
Medusa	805.3A	HR19A	600	8.7	5
Medusa	805.3B	HR19B	600	8.7	7
Medusa	836.6A	HR20A	600	25.0	4
Medusa	836.6B	HR20B	600	25.0	20
Medusa	875.7	HR21	600	11.1	4
Medusa	920.5	HR22A	600	21.5	6
Medusa	920.5	HR22B	600	21.5	10
Medusa	385.7	LR1	600	133.3	300
Medusa	427.2	LR2	600	13.3	60
Medusa	479.7	LR3	600	8.0	40
Medusa	543.1	LR4	600	1.7	12
Medusa	614.2	LR5	600	1.7	8
Medusa	682.2	LR6	600	1.4	6
Medusa	773.4	LR7	600	2.1	3
Medusa	881.7	LR8	600	5.6	3
UVES 6FIB	520	–	80	30	80
UVES 7+1/8FIB	580	–	60	20	40
UVES 8FIB	860	–	60	20	40

Table 1: Integration times in seconds for ThAr arcs and W flats, for both Robot calibrations and attached Screen flats. IFU/Argus times are twice the Medusa values. Configuration time is excluded. Attached flatfield times in the blue are very long and may be insufficient to flatfield accurately.

## **B calobBuild configuration files**

The daily calibration plan is coded with the help of the Calibration OB tool (`calob`). See [2] for details and the configuration syntax.



This page was intentionally left (almost) blank